Work Order ID 104962 Page 1 July-23-13 12:57:43 PM Item ID: D4092-1 Accept \*N900040100\* **Revision ID:** Item Name: Maintenance Step Start Date: 7/23/13 **Start Qty: 12.00** Cust Item ID: Required Date: 7/23/13 Req'd Qty: 12.00 Customer: Reference: Run Process Plan: MLJ Date: 13-07-75 Tooling: Approvals: Date: Date: SPC (Y/N): Date: Sequence ID/ Reject Operation Set Up/ Tool ID Tool # Plan Accept Reject Insp. Work Center ID Description Qty Run Hours Code Oty Number Stamp Draw Nbr **Revision Nbr** D4092 В 100 Cut blanks as per folio 0.0013/07/21 \*100\* Bandsaw Memo Jeaspa Bandsaw 110 0.00 13/08/04\_12 \*110\* HAAS 1 Memo HAAS CNC vertical machine #1 Mill as per Dwg and Folio FA935 Dwg Rev: Folio rev:

Deburr

										DQA,	. Date	:
NCR:	res / No				WORK ORDER NON-	CO	NFORM	MANCE / UPDATE				,
				_	<del>1</del>		_			QA Closed:	Date	<u>:</u>
Work Orde	or.				DISPOSITION			AGAINS	ST DE	PARTMENT	/PROCESS	,
	-··-				Rework	7		Skid-tube Crosstub	e 🗀	]	Water Jet	Engineering
Part N	No.				Scrap	ĺ	1	Machining Small Fa	ıb	Pro	d. Eng. Coor.	Quality
					Use-as-is	1	Therm	noforming Finishir	ng 🗀	Rec/Sto	re/Packaging	Other
NCR 1	No				Work Order Update	ر [		Large Fab Composit	te	]	Supplier	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Root		T		Descrij	ption of work order update		Initial	Action		Sign &		
Cause	Date	Step	Qty	C	or Non-conformance	Cr	nief Eng	Description		Date	Verification	QC Inspector
Doc/Data								-				
Equip/Tooling												·
Operator									٠			
Material												
Setup												
Other					•							
Process											,	'
Supplier								•				
Training			1									
Unapproved		<u></u>						·	·	<u> </u>		
					<del>-</del>	AUI	LT CATE	GORY				
Landi	ng Gear			_	General	_	7		_	٦.		<b>-</b>
•	Bending			<u></u>	Bend	$\perp$	Grain			Ovalized		Pressure/Forced
	Centre N	ot Conce	ntric to (	D/S	BOM/Route		Hardwa		$\perp$	Over/Under	tolerance	Temperature/Cure
	Cracks				Broken/Damaged	<u> </u>		on Incomplete		Part Incorred	<u> </u>	Weld
	Crushed,	/Crimped			Burrs		Instruct	ons Incomplete/Unclear		Part Lost/Mi	ssing	Wrong Stock Pulled
	Cuffs				Contamination		Mainte	nance		Part Moved		
	Heat Tre	at			Countersink		Mislabe	led	L	Positioned V	√rong	_
	Inspection	n Strip in	Tube		Cut Too Short		Misread			Power Loss/	Surge	Other

Offset

Out of Calibration

Out of Sequence

Outside Dimensions

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

Turning Sequence

Wave/Twist in Tube

Ripples in Bend

Torque Waves in Extrusion

Drill Holes

Drawing

Finish

Folio

\*140\*

140

HandFinish

Hand Finishing

Chemical Conversion Coat per QSI005 4.1

Conversion Coal per Q51005 4.1

Memo

0.00

0.00

12 May 13-8-9

											DQA:	Date	:
NCR: Y	es /	No				WORK ORDER NON-C	ON	<b>IFORN</b>	AANCE / UP	DATE	•		
	•										QA Closed:	Date	<u></u>
Work Orde	ar.					DISPOSITION				AGAINST DE	PARTMENT,	PROCESS	
WOIK OIGE						Rework			Skid-tube	Crosstube	]	Water Jet	Engineering
Part N	lo.					Scrap			Machining	Small Fab	Pro	d. Eng. Coor.	Quality
						Use-as-is			noforming	Finishing	Rec/Stor	e/Packaging	Other
NCR N	No					Work Order Update			Large Fab	Composite	)	Supplier	
Root					Descri	ption of work order update	li	nitial	Act	tion	Sign &		
Cause	D	ate	Step	Qty		or Non-conformance	Chi	ief Eng	Desc	ription	Date	Verification	QC Inspector
Doc/Data													
Equip/Tooling		-	ı	·									
Operator		İ											
Material											_		
Setup													
Other													
Process								!					
Supplier		]	ļ										
Training	Ш	l					}						
Unapproved						·				<del></del>			
							AUL	T CATE	GORY				
Landi	ng Gear				<del></del>	General	$\overline{}$	۱		r	1_ ,, ,		٦, ,,
	<del></del>	ding				Bend	-	Grain			Ovalized	⊢	Pressure/Forced
			Concer	itric to	O/S	BOM/Route	Н	Hardwa		_	Over/Under	<b>├</b>	Temperature/Cure
	Cra					Broken/Damaged	-	· '	on Incomplete		Part Incorred		Weld
i		shed/C	rimped			Burrs	_		ions Incomplete/	Unclear	Part Lost/Mi	ssing	Wrong Stock Pulled
	Cuff				-	Contamination	$\mathbf{H}$	Mainte		<u> </u>	Part Moved		
	—	t Treat			<u> </u>	Countersink	-	Mislabe		<u> </u>	Positioned V	_	المراجعة الم
	$oldsymbol{ol}}}}}}}}}}}}}}}}}}$		Strip in	Tube		Cut Too Short	$\vdash$	Misread	1		Power Loss/	Surge	Other
	Rip	ples in E	Bend		<u> </u> _	Drill Holes	$\vdash$	Offset					
	l ITar	que Wa	ves in E	xtrusio	n I	Drawing		Out of O	Calibration				

Out of Sequence

Outside Dimensions

Turning Sequence

Wave/Twist in Tube

Finish Folio

<b>Work Ord</b> <i>July-23-13</i> 12:.		4962			*104	1962*		*				Page 3
Item ID: Revision ID: Item Name:	D4092-1  Maintenance	Step	राज्यानयः – द्या		Accept	*N900	<b>04</b> 0	100	* S	etup Star Stop	1.71	S1* S2*
Start Date: Required Date Reference:	7/23/13	Start Qty: 12.00 Req'd Qty: 12.00		*12* *12*		Cust Item I Customer:	D:					. 12
Approvals:	Process Pl	an:	Date:		Tooling: SPC (Y/N):		ate:		R	un Star Stoj	17	R1* R2*
Sequence ID/ Work Center I		Operation Description Wing Walk as per dwg Q	S1005 4.4 E	ald BG	Set Up/ Run Hours	Tool 1D	Tool #	Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
*155* HandFinish Hand Finishing		Memo			0.00				[2	£ k	<u> </u>	8-00:
<sup>160</sup> *160*		QC3- Inspect Part Finish			0.00				/2 x		(	
QC Quality Control		Memo			0.00			-	<u> </u>		(	3-8-
*170		Identify as per dwg & Sto	ock Locatio	on <u>ST3</u> 70	)A 0.00				_/ <i>_</i> /_2_x	,		$\mathcal{A}$
Packaging		Momo			0.00			•	—-{-~ -/.\	· ·		

Packaging

										DQA:	Dat	:e:
NCR: Y	'es /	No				WORK ORDER NON-C	ONFOR	MANCE / UP	PDATE	QA Closed:	 Dat	·e·
						DISPOSITION			AGAINST DE			
Work Orde	er:					Rework		Skid-tube	Crosstube	1	Water Jet	Engineering
Part N	lo					Scrap Use-as-is	The	Machining	Small Fab Finishing	-	d. Eng. Coor. re/Packaging	Quality
NCR N	lo					Work Order Update	:	Large Fab	Composite	]	Supplier	
Root						ption of work order update	Initial		ction	Sign &		
Cause		Date	Step	Qty	C	or Non-conformance	Chief En	g Desc	cription	Date	Verification	1 QC Inspector
Doc/Data		!										
Equip/Tooling												
Operator												
Material		-						1				
Setup												
Other		ŀ										
Process												
Supplier												
Training											1	
Unapproved					_							_
						F/	AULT CAT	EGORY				<u></u>
Landi	ng Gea	ar				General			-	<b>-</b>	·	
	Ве	ending				Bend	Grain			Ovalized		Pressure/Forced
	Ce	entre No	t Concer	itric to	o/s	BOM/Route	Hardy	vare .		Over/Under	tolerance	Temperature/Cure
	Cr	acks				Broken/Damaged	inspe	tion incomplete		Part Incorre	ct	Weld
	Cr	ushed/C	rimped			Burrs	Instru	ctions Incomplete,	/Unclear	Part Lost/M	issing	Wrong Stock Pulled
	Cı	uffs				Contamination	Main	tenance		Part Moved	_	
	Пн	eat Treat	ţ			Countersink	Misla	peled	[	Positioned V	<b>V</b> rong	
	Пıп	spection	Strip in	Tube		Cut Too Short	Misre	ad		Power Loss/	'Surge [	Other
	Ri	pples in	Bend			Drill Holes	Offse			_		

Out of Calibration

Out of Sequence

Outside Dimensions

Turning Sequence

Wave/Twist in Tube

Ripples in Bend

Torque Waves in Extrusion

Drawing

Finish Folio

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

Work Order ID 104962 Page 4 July-23-13 12:57:43 PM Item ID: D4092-1 Accept \*N900040100\* Setup Start Revision ID: Stop Maintenance Step Item Name: \*12\* Start Date: 7/23/13 Start Qty: 12.00 Cust Item ID: Required Date: 7/23/13 Req'd Qty: 12.00 Customer: Reference: Run Start Process Plan: \_\_\_ Approvals: Date: Tooling: Date: Stop QC: Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Accept Reject Reject Insp. Work Center 1D Description Run Hours Code Qty Qty i Number Stamp 180 QC21- Final Inspection - Work Order Release 0.00 \*120\* MLJ 13-08-30 QC 0.00 Memo

Quality Control

									DQA:	Date	*
NCR: Y	es / No				WORK ORDER NON-	CONFO	RMANCE / UF	PDATE	QA Closed:	Date	:
Work Orde	r.			· · · · · · · · · · · · · · · · · · ·	DISPOSITION			AGAINST DE		· · · · · · · · · · · · · · · · · · ·	*******
Part N	0				Rework Scrap Use-as-is Work Order Update	The	Skid-tube  Machining rmoforming Large Fab	Crosstube Small Fab Finishing Composite	-1	Water Jet d. Eng. Coor. re/Packaging Supplier	Engineering Quality Other
Root				Descri	ption of work order update	Initial	Ad	ction	Sign &		
Cause	Date	Step	Qty	1	or Non-conformance	Chief En	g Desc	cription	Date	Verification	QC Inspector
oc/Data quip/Tooling Operator Material Setup Other Process Supplier Training Unapproved											
						AULT CAT	TEGORY		• •		<del></del>
Landir	ng Gear			_	General				-	-	7
	Bending Centre N Cracks Crushed/ Cuffs Heat Trea Inspectio Ripples in Torque V	Crimped at in Strip in in Bend	Tube		Bend BOM/Route Broken/Damaged Burrs Contamination Countersink Cut Too Short Drill Holes Drawing	Instru Mair Misla Misre Offse	ware ction Incomplete actions Incomplete, atenance beled ad	/Unclear	Ovalized Over/Under Part Incorre Part Lost/Mi Part Moved Positioned V Power Loss/	ct issing Vrong	Pressure/Forced Temperature/Cure Weld Wrong Stock Pulled Other
1	Turning S	Sequence			Finish	Out o	f Sequence				4

Outside Dimensions

Wave/Twist in Tube

Folio

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

## **Picklist Print**

July-23-13 12:57:43 PM

Work Order ID:

104962

Parent Item:

D4092-1

Parent Item Name:

Maintenance Step

Start Date: 7/23/13

Required Date: 7/23/13

Page 1

**Start Qty: 12.00** 

Required Qty: 12.00

Comments:

Ipp Rev:A New Issue 10-05-31 JLM Verified By:DD

IPP REV:B AS PER ECN 11-

	639 JLM VERIFIE	ED BY:DD											
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2761-108		— Manufactured	No			100	f	659.2035	2.5	31.578947			11
Extrusion (HPK)										<del></del>		<del></del>	
				<b>Location</b>		Loc Oty	<u>Lo</u>	c Code					
				MAT007		659.20354					-A	13/07/31	
				<b>-</b> 8020	)6	659 20354			3	ડેંડ	$M_{\mathbf{L}}$	1717/12	1

		•
	DOΔ·	Data
	DQA:	Date:

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

											QA Closed:	Dat	e:
Work Orde	er:					DISPOSITION				AGAINST DE	PARTMENT	/PROCESS	
Part N	 lo					Rework Scrap Use-as-is Work Order Update	T	M hermo	Skid-tube  Nachining  oforming  Large Fab	Crosstube Small Fab Finishing Composite	i	Water Jet d. Eng. Coor. re/Packaging Supplier	Engineering Quality Other
Root				-	Descri	ption of work order update	Initi	al	Ac	tion	Sign &		
Cause	Da	ate	Step	Qty	•	or Non-conformance	Chief	Eng	Desc	ription	Date	Verification	QC Inspector
Doc/Data									•				
Equip/Tooling		i						1					
Operator													
Material													
Setup													
Other_								ļ			 		
Process											,		
Supplier					;								
Training													
Unapproved						·							
							AULT C	ATEG	ORY				
Landi	ng Gear					General				_	1	-	
	Ben	_			<u> </u>	Bend	Gra			<u> </u>	Ovalized		Pressure/Forced
	Cen	tre No	t Concer	ntric to	o/s	BOM/Route	$\vdash$	rdwar		ļ <u></u>	Over/Under	+	Temperature/Cure
	Crac				<u> </u>	Broken/Damaged	$\mathbf{H}$	-	on Incomplete	<u> </u>	Part Incorred	}-	Weld
	<del></del>		rimped		<u> </u>	Burrs	$\boldsymbol{\vdash}$		ons Incomplete/	Unclear	Part Lost/Mi	ssing	Wrong Stock Pulled
,	Cuff	Ş			_	Contamination	$\vdash$		nance	L	Part Moved		
	Hea	t Treat			_	Countersink	-	slabele	e <b>d</b>	<u> </u>	Positioned V		_
	insp	ection	Strip in	Tube		_Cut Too Short	₩.	sread			Power Loss/	Surge [	Other
	Ripp	oles in	Bend			Drill Holes	$\boldsymbol{\vdash}$	fset					
	— ;	-	aves in E		n L	Drawing	$\vdash$		alibration				
	Turi	ning Se	quence			Finish	∐0 <sub>u</sub>	it of Se	equence				
	l lway	re/Twi	st in Tub	e.	l	Folio	I lou	itside (	Dimensions				

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

DART AEROSPACE LTD	Work Order:	104962
Description: Maintenance Step	Part Number:	D4092-1
Inspection Dwg: D4092 Rev: B		Page 1 of 1

## FIRST ARTICLE INSPECTION CHECKLIST


Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
30.06	+/-0.030	30.0613	\ \		cre Hoss *1	
0.19	+/-0.030	.1845	✓	·	174-04	Caliper
1.25	+/-0.030	1.249				
1.38	+/-0.030	1.380				
0.25	+/-0.030	ุ่วฯร				
R0.25	+/-0.030	- 32				
2.50	+/-0.030	2,497				
Ø0.201	+0.005/-0.001	١٥٢,	/,		-	
0.30	+/-0.030	, 301				
4.78	+/-0.030	4.78	~			
1.69	+/-0.030	1.69	-			
2.96	+/-0.030	2,96				
0.030	+/-0.010	,025				
0.20	+/-0.030	- Joc2	7			
0.50	+/-0.030	,50¢1	V			
0.035	+/-0.010	, 034	· · · · · · · · · · · · · · · · · · ·			
0.390 x 100°	+/-0.010 x 0.5°	. 393×00°		***************************************		
1.500	+/-0.130	1-499				
0.50	+/-0.030	,449		· · ·		
1.25	+/-0.030	1.25				
0.69	+/-0.030	. 688				
0.38	+/-0.030	.375				
0.69	+/-0.030	- G88				

	M/D.A				
Measured by:	11H /And	Audited by:	Pr	eliminary Approval:	
Date:	13/08/04	Date: 13 · 8 ·	7	Date:	
	13/8/06				

		/ \$ / <b>B</b> / 06	<del></del>	
Rev	Date	Change	Revised by	Approved
,A	12.05.15	New Issue	KJ )(\_	L. A. A
' B	13.06.18	Dimension 2.96 was 2.69	KJ 75	

				•	
			•		
		•			
			•		
-					
	•				
					•
c •					•

MAINTENANCE STEP 45:35 1 C 1 --D4035 1 -D4093 1 MAINTENANCE STEP BRACKET BRACKET D4093-5 BRACE 12 MS21042L3 2 MS24694-S54 8 MS24694-S55 2 MS24694-S56 12 NAS1149D0332J NUT SCREW SCREW SCREW WASHER



104962 MLS 1307-25

**D4092-041 MAINTENANCE STEP ASSEMBLY** 

5




		•			
В	REDRAV	√N; LOWERED	FOR AESTHETICS	RF	11,07,27
Ā	NEW ISS	iUE		RF	10 09.16
REV.	<u> </u>	DESCRIPTION		BY	DATE
DESIG	N	RF	DART AEROSPACE	- USA	INC.
DRAW	N	RF	KENT, WA		,
CHEC	KED	140	DRAWING NO.		REV. B
MFG. A	APPR.	91	□ D4002		SHEET 1 OF 6
APPRO	VEO	14	TITLE		SCALE
DE AP	PR.	-4	MAINTENANCE STER	P ASS	Y мтs
DATE	11.0	7.27	COPYRIGHT © 2010 BY DART ARE BILLOCOLUMNY IS HENLY; MO COMPRENTIL, MOS (LPRLY); ADT TORT UNCOYOU AME PURPOSE DIS CONTROL DATE WAS MOTTHS PROMISSION DAY WAS	OW THE CHARGE	S CONDITION THAT IT IS

3

2

्रात्र सम्बद्धाः । च्या	
	·
	·
	- Company And


	्रीन्ड		
;	x	$\mathcal{Q}^{T_{i}N_{i}}$ .	AMMIENANCE STEF A 45 (MIN /
3 4	. <u>1</u>	0/10% 04093+1 04093+1	HANTERANCE STEP BRACKET BRACKET
. 5	2	_D40 <u>9</u> 5-5	BRACKET
, 6	12	MS21042L3	NUT
7	2	MS24594-S54	SCREW
8	8	MS24694-S55	SCREW
9	.2	; MS24694-S56	SCREW
10	12	NAS1149D0332J	WASHER






DESIGN	RF	DART AEROSPACE USA, INC.		
DRAWN	RF	KENT, WA		
CHECKED	140	DRAWING NO. REV. B		
MFG. APPR.	91	D4092 SHEET 2 OF 6		
APPROVED	NP	TITLE SCALE		
DE APPR.	-#-	MAINTENANCE STEP ASS'Y NTS		
DATE 11.0	7.27	COPYRIGHT © 2016 BY DART AEROSPACE USA, INC.  Pel COUNTRY of Many 2 are convergent, and a survey of our tenders process BY 7 6 act to 32 abound a wearing on control convergent by taken grant region without		

•			
	•		
		•	
		• •	
		•	
		•	
	•		
		·	
•		,	





## **D4092-041 MAINTENANCE STEP ASSEMBLY**




NOTES:
1) MATERIAL: N/A
2) FINISH; N/A
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: PER QSI 044 6.1
7) WEIGHT: 5.37 lbs
8) TORQUE SCREWS UP TO 15-25 in-lb (1.7-2.8 N-m)
9) GRIP CUTOUT TOWARD CENTER


С


DESIGN	RF	DART AEROSPACE USA, INC.		
DRAWN	RF	KENT, WA		
CHECKED	140	DRAWING NO.	REV. B	
MFG. APPR.	91	D4092 <sub>SHEE</sub>	T3OF6	
APPROVED	10	TITLE	SCALE	
DE APPR.	-H	MAINTENANCE STEP ASS'Y	NTS	
DATE 11.0	7.27	COPYRIGHT & 2010 BY DART ADROSPACE USA, INC. THE DOCUMENT IN MINITER HIS CONFIDENTIAL US & SUPPLED DIVINE DIMENSI CONFIDENTIAL US & SUPPLED DIVINE DIMENSI CONFIDENTIAL US IN SUPPLED DIVINE TO SUPPLE CONFIDENTIAL TO SUPPLE CONFIDENTIAL USA INC.  WINTERS REPROSPRIENT WITH USA WAY FOR CONFIDENTIAL USA INC.		

t.

		Management of the common commo
•		
		•
		•
		$\cdot$
		·
	•	
		·
		•
		·
		·
	•	
•		,
		and the first war was a still a grown








## **D4092-042 MAINTENANCE STEP ASSEMBLY**


NOTES:	
NOTES: 1) MATERIAL: N/A	
2) FINISH: N/A	
Z) FINISH: IN/A	


2) FINISH: N/A
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: PER QSI 044 6.1
7) WEIGHT: 5.37 lbs
8) TORQUE SCREWS UP TO 15-25 in-lb (1.7-2.8 N-m)
9) GRIP CUTOUT TOWARD CENTER

DESIGN	RF	DART AEROSPACE USA, INC.		
DRAWN	RF	KENT, WA		
CHECKED	NP	DRAWING NO.	REV. B	
MFG. APPR.	91	D4092	SHEET 4 OF 6	
APPROVED	10	TITLE	SCALE	
DE APPR.	-#	MAINTENANCE STEP ASSY N		
DATE 11.0	7 27	COPYRIGHT @ 2010 BY DART AEROSPACE USA, INC. Deconcern arrest is reconfigurate and supplied on the service operating that it is		

···			
		•	
	,		
	•		
			•
7			
, ;			
•			
	•		
		•	
•			
		•	
, s			
•			







D4092-1 MAINTENANCE STEP (MAKE FROM D2761 EXTRUSION)

NOTES:
1) MATERIAL: MAKE FROM D2761 EXTRUSION
2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
31 MASK RECTANGULAR CUTOUT PRIOR TO APPLICATION OF ANTI-SKID
4) UNITS: INCHES : PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX, NOT REQUIRED TO DEBURR GRIP AREA
6) IDENTIFICATION: INA
7) WEIGHT: 1.97 lbs
8) MACHINE 0.69 x 0.69 GRIP 0.030 DEEP AT 45 \* PATTERN 0.38 APART


C

8

DESIGN	RF	DART AEROSPACE USA, INC.	
DRAWN	RF	KENT, WA	
CHECKED	140	DRAWING NO.	REV. B
MFG. APPR.	91	D4092 <sub>SHE</sub>	T 5 OF 6
APPROVED	NA	TITLE	SCALE
DE APPR.		MAINTENANCE STEP ASS'Y	NTS
DATE 11.07.27		COPYRIGHT © 2010 BY DART AERDSPACE USA, INC.  146 DOCUMENT A PRIVATE WORD TO THE OUT OF THE CONTROL OF THE ARREST OF THE CONTROL OF THE ARREST OF THE CONTROL OF THE ARREST OF THE CONTROL	

5

-	
	•
	<b>.</b>
	·.
	•
$\cdot$	



Ī

- T

1

7 . 'AB